

Message

From: Steve Wright [swright@cfaluminum.com]
Sent: 7/5/2017 8:29:37 PM
To: Cirian, Mike [Cirian.Mike@epa.gov]
CC: John.Stroiazso@glencore-ca.com; Michael Ritorto [mritorto@rouxinc.com]; Andrew Baris [abaris@rouxinc.com]
Subject: South pond dike erosion continues
Attachments: 20170705_110708.jpg; 20170705_110736.jpg; 20170705_110748.jpg; 20170705_110758.jpg; 20170705_111503.jpg; 20170705_111238.jpg; 20170705_110930.jpg

<<20170705_110708.jpg>> Mi <<20170705_110736.jpg>> ke
<<20170705_110748.jpg>> -
<<20170705_110758.jpg>>
I <<20170705_111503.jpg>> w <<20170705_111238.jpg>> en
<<20170705_110930.jpg>> t down and looked at the south pond dam/dike today. It's been a week or so since I checked on it. It continues to be eroded. The river is now hitting the south corner of the piling itself. If the river goes up a couple feet, it may enter the pond. Attached are photos. Mike Ritorto is compiling and summarizing the south pond data. We are available to have a call about options for the south pond. We may want to consider putting some rip-rap on the corner of the pond to prevent further erosion and the possibility of the river entering the pond. Regulatory permitting processes can be complex when working on or near the river, so we thought you may have some ideas on how to proceed. Do you want to have a call tomorrow or this week to discuss options? Let me know your availability. Thank you.

Steve Wright